

HIGHWAY SAFETY RESEARCH CENTER CURRENT CAR SEAT RECALL LIST

Last Revision: January 4, 2022

Download this list & sign up for email notification of updates: buckleupnc.org/car-seat-recall-list

About Car Seats and Recalls

It is very important to pay attention to recall notices and for parents to check if their seats are safe to use. Recalls can be issued for any failure to meet Federal Motor Vehicle Safety Standard 213. Most recalls are issued due to reasons related to the crashworthiness of the car seat, but some recalls are for deviations from the standards related to labeling requirements, flammability of the upholstery or padding, or for parts that may come loose and pose a choking hazard. All recalls should be corrected.

Car seats are required to have a label indicating the manufacturer, model information, and date of manufacture. Car seats should not be used if these labels are missing. It is important for people to register their car seat by either mailing the registration card to the manufacturer or by contacting the manufacturer directly.

In cases where the manufacturer of a recalled seat has gone out of business or discontinued replacement programs, parents are advised to discontinue use of the seat. Discarded seats should be taken apart and stripped of upholstery, padding and straps and then destroyed by having them crushed to prevent others from using them.

To report any suspected car seat defects, call the National Highway Traffic Safety Administration Auto Safety Hotline at 888-327-4236 / (TTY): 800-424-9153.

About Older Car Seats and Recalls

The older model list includes recalled seats that are now 10 or more years old. Caregivers will sometimes choose to use older car seats even though it not recommended. Knowing that a particular model is under recall should help to encourage the caregiver to destroy the older seat and obtain a new one.

About the HSRC Recall List

The UNC Highway Safety Research Center (HSRC) car seat recall list is updated as soon as possible after recall notifications are announced and after the information can be verified for completeness and accuracy. Users of this (or any other) recall list should remind parents/caregivers to contact the manufacturer to be certain whether or not a particular car seat is affected by any recalls and how to proceed with repairs or replacement.

Instructions for Using the HSRC Recall List

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the manufacturer, model, and dates of manufacture match any of the listings. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

For further information, contact:

Bevan Kirley or Kristel Robison

The University of North Carolina Highway Safety Research Center

800-672-4527 x2 or cps@hsrc.unc.edu

www.buckleupnc.org/car-seat-recall-list

This Page Intentionally Left Blank

The following lists identify recalls and safety notifications for car seats known by the UNC Highway Safety Research Center (HSRC) as of January 4, 2022. This list is updated by HSRC as soon as possible after recall notifications are announced. The most recent additions to the list are denoted by >>. Updated versions are available on-line at www.buckleupnc.org/car-seat-recall-list

Car seats are required to have labels indicating the manufacturer, model name and number, and date of manufacture. Model names and numbers are listed for most of the recalls. For the model numbers, "x" means that more numbers or letters follow. If the label is missing on a car seat, contact the manufacturer to see if it can be identified through other information. **A car seat should not be used if its recall status cannot be determined because the model name, model number, date of manufacture or manufacturer is not available.**

Car seats manufactured before 1981 were not required to be crash tested and must not be used. Car seats beyond their expiration dates should also not be used. Most car seats expire after 6 years from the date of manufacture, but expiration dates vary by manufacturer and model. Most manufacturers stamp their car seats, on a label or in the shell, with an expiration date, typically six to eight years from the date of manufacture. If needed, you can call the manufacturer. **Models older than ten years and under recall are included on a separate list with a separate index** for use as a reference. The index for older models can be found following the last page of the "Models Less Than 10 Years Old" list and the list of older models with recalls follows the second index. **The "Models At Least 10 Years Old" list was last revised April 5, 2021.**

Some of the recalls/notifications for car seats on this list may be more or less date- or lot-specific than what is listed. More detailed information should be obtained through the manufacturer and **it is the manufacturer who can and should make the final determination if a specific car seat is subject to recall.**

Some of the recall notices are related to problems that do not make the seats unsafe in a crash, but **all problems should be corrected.** Phone numbers are provided when a corrective action can be taken. The manufacturer should advise you whether to continue using your current car seat or to obtain another one until the problem can be corrected.

In cases where the manufacturer has gone out of business or discontinued replacement programs, you are advised to destroy the car seat and obtain and use another one as soon as possible. Do not throw unsafe models in the trash where they can be picked up and used by others. Discarded car seats should be destroyed by having them crushed. At the very least, they should be taken apart and stripped of upholstery, padding and straps to prevent others from using them.

To report any suspected car seat or vehicle safety defects, contact the National Highway Traffic Safety Administration Auto Safety Hotline: (888) 327-4236 / (TTY): 800-424-9153.

Refer to Page 13 for the Index of Recalls and Safety Notifications

Download this list & sign up for email notification of updates: buckleupnc.org/car-seat-recall-list

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
	4moms			4moms - 888-614-6667 / www.4moms.com
1)	Infant Car Seat	1032	07/01/16- 10/31/16	The hooks that lock the carrier into the base can stick and fail to attach the carrier to the car seat base. Contact mfg. for free replacement seat.
2)	Alcot (Childcare)			REFER TO OLDER MODELS LIST
3)	All Our Kids			REFER TO OLDER MODELS LIST
4)	Alpha Elite (Dorel)			REFER TO OLDER MODELS LIST
5)	Alpha Sport (Dorel)			REFER TO OLDER MODELS LIST

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
6)	American Motors			REFER TO OLDER MODELS LIST
	Angel Guard (Merritt Manufacturing)			317-409-0146 - www.merrittcarseat.com
7)	AngelRide Car Bed	All Models	08/08/19- 10/24/19	The internal harness may not have been properly sewn where the buckle is attached. Contact mfg. for free replacement harness.
	babidéal (Dorel China America)			877-657-9546 - www.babideal-us.com
8)	Storm Booster	BC901BPXL	02/28/19	The label attached to the fabric cover may not have the required safety warnings and instructions. Affected models do not comply with FMVSS 213 labeling requirements. Contact mfg. for free replacement fabric cover.
	Baby Jogger			800-241-1848 - www.babyjogger.com
9)	City GO Infant Car Seat	BJ64510, BJ64529	11/03/14- 04/30/15	The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
10)	City GO Infant Car Seat Base	BJ80400, BJ61500	11/03/14- 04/30/15	The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
11)	City Mini Infant Car Seat/ Stroller System	BJ72510	11/03/14- 04/30/15	The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
12)	Vue Lite Infant Car Seat/ Stroller System	BJ70411, BJ70424, BJ70431	11/03/14- 04/30/15	The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
	Baby Trend			800-328-7363 - www.babytrend.com
13)	Hybrid 3-in-1 LX	FB48417, FB58181	07/14/16 - 07/23/16	The center adjuster may detach in a crash when used in the harnessed mode with a child weighing more than 40lbs. Contact mfg. for free replacement seat.
14)	TrendZ Fastback 3-in-1	FB60070, FB60408	10/01/11- 07/31/13	The harness buckle may become stuck in a latched condition so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
15)	Babyhood Industries			REFER TO OLDER MODELS LIST
16)	Basic Comfort			REFER TO OLDER MODELS LIST
17)	Beatrix Potter (Dorel)			REFER TO OLDER MODELS LIST
18)	Bertini (Dorel)			REFER TO OLDER MODELS LIST
19)	Bolform Corp.			REFER TO OLDER MODELS LIST
	Britax			888-427-4829 / 704-409-1699 - Britax.Recall@britax.com / www.britaxusa.com
20)	Advocate 70-G3	E9LG81A, E9LG83x, E9LL21A, E9LL23P, E9LL23Y	06/01/12- 08/31/12	Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.
21)	Advocate ClickTight	E1A025Q, E9LT95N, E9LT95Q, E9LT95Z	08/01/14- 07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Britax (continued)				
22)	B-Safe 35 B-Safe 35 XE	E9LU65M, E9LU65P, E9LU63F, E9LU66R, EXLU65M, E9LS63F	10/01/14- 07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit www.bsaf35recall.com for more information.
23)	B-Safe 35 Travel System B-Agile Travel System	S914900, S915400, S915200, S01635200, S921900	10/01/14- 07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit www.bsaf35recall.com for more information.
24)	B-Safe 35 B-Safe 35 Travel Systems	E1A183F, E1A185x, E1A186R, E1A203F, E1A205x, E1A206x, E1A207E, E9LU65V, E9LU66x, E9LU67x, EXA185M, S02063xxx, S03803xxx, S04144xxx, S04145000, S04402800, S04884xxx, S04975600, S04978900, S05260200, S06020xxx, S06147100, S921800	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
25)	B-Safe 35 Elite B-Safe 35 Elite XE	E9LS55T, E9LS56P, E9LS55U, E9LS66C, E9LS65U	10/01/14- 07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit www.bsaf35recall.com for more information.
26)	B-Safe 35 Elite B-Safe 35 Elite Travel Systems	E1A215x, E1A216P, E1A221Q, E1A225x, E1A226L, E9LS5xx, EXA216L, S01298600, S02063xxx, S02064000, S04281xxx, S04628500, S06018800, S06020xxx, S06051300, S923700	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
27)	B-Safe BOB 35	E9LT34x, E9LT35X, EXLT34A	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
28)	Boulevard 70- G3	E9LJ91x, E9LJ92E, E9LJ93P, E9LJ93S, E9LK91A	06/01/12- 08/31/12	Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Britax (continued)				
29)	Boulevard ClickTight	E1A015Q, E1A016A, E1A016H, E1A135Q, E9LT85Q, E9LT85S, E9LT86A, E9LT86F, E9LT86G, E9LT86H	08/01/14-07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.
30)	Companion	E9L14, E9L20, E9L80	All	Consumer Advisory - NOT A RECALL: Britax advises that the user should adjust the carrier handle so that it is completely down and behind the carrier after installation in the vehicle with or without the base assembly. Contact mfg. for additional info.
31)	Marathon ClickTight	E1A005R, E1A006B, E1A116L, E9LT71Q, E9LT75R, E9LT76B, E9LT76L, E9LT76N, E9LT76P, EXA116L	08/01/14-07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.
32)	Pavilion 70-G3	E9LK31x, E9LK32x, E9LK33Q, E9LL11x, E9LL12x	06/01/12-08/31/12	Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.
33)	Century Products	REFER TO OLDER MODELS LIST		
34)	Chicco	REFER TO OLDER MODELS LIST		
35)	Chrysler	REFER TO OLDER MODELS LIST		
	Clek	866-656-2462 - www.clekinc.com		
>> 36)	Flo	FL15, FL16, FL17, FL18, FL19	07/05/14-05/20/21	It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact mfg. for a remedy kit.
>> 37)	Foonf	FO12, FO14, FO15, FO16, FO17, FO18, FO19	12/03/12-05/20/21	It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact mfg. for a remedy kit.
>> 38)	Liing	LG19U1	03/27/19-09/14/20	A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact mfg. for a remedy kit.
>> 39)	Liing	LG19U1	03/27/19-02/22/21	The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact mfg. for a remedy kit.
>> 40)	Liingo	LGO20U1	05/20/20-09/14/20	A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact mfg. for a remedy kit.
>> 41)	Liingo	LGO20U1	05/20/20-02/22/21	The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact mfg. for a remedy kit.
42)	Collier-Keyworth	REFER TO OLDER MODELS LIST		
	Combi USA	800-992-6624 / 803-548-6633 - www.combi-intl.com		
43)	BabyRide	378099	05/01/16-08/31/19	The 1-inch-wide front webbing strap used to adjust the harness does not meet FMVSS 213 breaking strength requirements and in certain circumstances, may not adequately restrain a child during a crash. Contact mfg. for more information.
44)	Coccoro	8220	01/06/09 - 12/05/12	Harness webbing fails to meet FMVSS 213 minimum breaking strength requirements. Contact mfg. for free harness replacement kit and instructions. The seats can continue to be used until the kits are made available and repairs are made.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Combi USA (continued)				
45)	Coccoro	8220x	01/01/09- 06/29/16	Too much force can be placed on the child when the car seat is installed forward-facing with only the vehicle's lap belt. All other installation methods are not affected. Contact mfg. for a cover to add to the bottom of the seat.
46)	Zeus 360	8836	02/25/09 - 05/24/12	Harness webbing fails to meet FMVSS 213 minimum breaking strength requirements. Contact mfg. for free harness replacement kit and instructions. The seats can continue to be used until the kits are made available and repairs are made.
47)	Compass Baby		REFER TO OLDER MODELS LIST	
	Cosco (Dorel)		Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com	
48)	Comfy Carry	IC123 FSM	05/01/11- 04/25/12	Some models were sold without a base and therefore did not provide lower LATCH attachments as required by FMVSS 213. Carriers can safely be installed without the base using the seat belt. Contact mfg. to obtain a base.
	Diono		855-463-4666 - www.us.diono.com	
49)	Cambria 2	31200-US-01, 31201-US-01, 31202-US-01	09/05/20- 11/30/20	When used as a highback booster, a crack between the headrest and backrest can occur in a crash, allowing the headrest to separate. Affected products have serial numbers that start with 648762, 648801, 648802, 648803, 648825, 648842, 648843, 648844, 648846, 648847, 648925, or 648926. Contact mfg. for a replacement backrest/headrest.
50)	Olympia	30100	04/12/14- 03/31/15	The seat may not adequately protect a child in a crash when used in harnessed mode and installed forward-facing.
51)	Pacifica	30400, 300000	04/12/14- 05/13/16	Children who weigh more than 65 lbs: Seats installed forward-facing (with any installation method) require the use of a top tether for children weighing more than 65 lbs in harnessed mode. If no top tether anchor is available, use the seat in booster mode.
52)	Radian R100	16600, 16000	01/03/14- 09/05/17	
53)	Radian R120	16800, 16000	01/03/14- 08/30/17	Children who weigh 65 lbs or less: Seats installed forward-facing using only the lap belt require the use of the top tether for children who weigh 65 lbs or less in harnessed mode. If no top tether anchor is available, contact mfg. for a free repair kit.
54)	Radian RXT	16900, 16000	11/25/13- 09/05/17	
55)	Rainier	30300, 300000	04/12/14- 09/05/17	
56)	Disney (Dorel)		REFER TO OLDER MODELS LIST	
57)	Downunder		REFER TO OLDER MODELS LIST	
58)	Eddie Bauer (Dorel)		REFER TO OLDER MODELS LIST	
	Evenflo		800-525-2472 / 800-233-5921 / 800-490-7497 - www.evenflo.com	
59)	Big Kid Booster	30911173AD, 3091967AD, 30911118AD, 30911120D	ALL	The affected seats - originally intended for display models - were packaged without the instruction manual or the required registration card. Otherwise, including crashworthiness, they were fully compliant with FMVSS 213. However, some seats were inadvertently shipped to institutional customers to be given to families. None of the affected units were sold at retail stores. Affected seats end with the letter "D" and have a label stating: "DISPLAY ONLY – NOT INTENDED FOR SALE," located on the back of the booster seat headrest. Contact mfg. for remedy kit.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Evenflo (continued)				
60)	Chase Factory Select Chase LX Chase Select	306xxx	06/12/12- 10/03/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
61)	Chase DLX Chase LX	329xxx	08/23/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
62)	Embrace 35	3151198, 3151953, 31511xxx, 31521138, 46811xxx, 48111xxx, 48411xxx, 52911307A, 55311xxx, 52921040	12/01/11- 05/31/13*	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. *NOTE: Not all Embrace 35 models in the 12/01/11-05/31/13 date range are impacted. Contact mfg. for specific dates and replacement buckle if needed.
63)	Evolve 3-in-1	34411700, 34411741	02/26/15- 02/09/16	The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.
64)	Express Factory Select	329xxx	08/23/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
65)	Maestro Maestro Factory Select	310xxx	08/22/11- 10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
66)	Momentum 65 Momentum 65 DLX	385xxx	03/04/13- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
67)	Secure Kid 100 Secure Kid 300 Secure Kid 400 Secure Kid LX Secure Kid LX Factory Select	308xxx	12/13/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
68)	Snugli All-in-One	346xxx	10/02/12- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Evenflo (continued)				
69)	Snugli Booster	308xxx	12/13/11-03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
70)	Snugli Embrace	3071136535	06/01/12-11/30/12	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for a free repair kit.
71)	SureRide DLX	371xxx	06/20/12-10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
72)	Symphony 65 DLX Symphony DLX Symphony LX	345xxx	10/02/12-08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
73)	Symphony Symphony 65 E3	346xxx	10/02/12-08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
74)	Titan 65 Titan 65 Factory Select	371xxx	06/20/12-10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
75)	Transitions 3-in-1	34411029, 34411686, 34411695	12/18/14-01/29/16	The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.
76)	Fisher Price		REFER TO OLDER MODELS LIST	
77)	Ford		REFER TO OLDER MODELS LIST	
78)	General Motors		REFER TO OLDER MODELS LIST	
79)	Gerry		REFER TO OLDER MODELS LIST	
	Graco		800-345-4109 - www.gracobaby.com	
80)	Aprica A30	All Models	07/01/11-04/30/12	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
81)	Argos 70 / Argos 70 Elite	All Models	05/01/11-07/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Graco (continued)				
82)	Classic Ride	1812930	03/01/14- 02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
83)	Classic Ride 50	All Models	10/01/11- 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
84)	ComfortSport	All Models	10/01/10- 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
85)	ComfortSport	1794333, 1813040	03/01/14- 02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
86)	Extend2Fit	1954477	11/27/15- 01/20/16	The recline labels on affected models do not meet FMVSS 213. Labels on the side of affected car seats, including the recline label, may not be in the same language (i.e. all English on one side of the car seat and all Spanish on the other side). Recall does not affect the safety performance of the seat. Contact mfg for replacement labels.
87)	Head Wise 70 with Safety Surround	All Models	01/01/12- 07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
88)	Milestone	1910130, 1923980, 1926538, 1926539	07/09/15- 10/09/15	The labels on affected seats do not include specific phrasing about how to install the car seat, as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for free replacement labels.
89)	My Ride 65 / My Ride 65 with Safety Surround	All Models	04/01/09- 07/31/13 & 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
90)	My Ride 65	1794334, 1813015, 1813074, 1853478, 1871689, 1872691, 1877535, 1908152	05/16/14 - 08/01/14	The harness webbing used on certain My Ride 65 convertible car seats do not meet FMVSS 213 requirements for breaking strength. Harnesses with the webbing tag code "2014/06" are the only models affected by this recall. Contact mfg. for replacement harness. Consumers may continue to use the My Ride 65 convertible car seats while waiting for a replacement kit.
91)	My Ride 70	All Models	05/01/12- 07/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
92)	My Size 70	All Models	01/01/12- 07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
93)	Nautilus 3-in-1 / Nautilus Elite / Nautilus Plus	All Models	10/01/07- 07/31/13 & 08/19/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
94)	Ready Ride	All Models	10/01/10- 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Graco (continued)				
95)	Ready Ride	1924519, 1924520	03/01/14- 02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
96)	Size4Me70	All Models	01/01/12- 07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
97)	Smart Seat / Smart Seat with Safety Surround	All Models	12/01/10- 09/30/13 & 10/09/13; 12/25/13; 1/10/14	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
98)	SnugRide, SnugRide Classic Connect	All Models	03/01/11- 05/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
99)	SnugRide 30 SnugRide Classic Connect 30	All Models	07/01/10- 01/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
100)	SnugRide 35 SnugRide Classic Connect 35	All Models	05/01/11- 01/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
101)	SnugRide Click Connect 40	All Models	06/01/12- 12/31/12	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
102)	TurboBooster	1963973, 1963974, 1963975, 1963976, 1967886, 1975173	12/22/15- 04/05/16	Instructions are missing the information required by FMVSS 213 that the seats should be securely belted to the vehicle at all times, even if the seat is unoccupied. Recall does not affect the safety performance of the seat. Contact mfg. to obtain missing instructions.
Harmony			877-306-1001 / www.harmonyjuvenile.com	
103)	Big Boost Deluxe	All Models	11/01/15- 06/24/17	In the event of a crash, a child's chest may experience forces that exceed FMVSS 213 limits. Owners should contact Harmony customer service for more information.
104)	International	REFER TO OLDER MODELS LIST		
Kiddy USA			855-925-4339 / info@kiddyusa.com / www.kiddyusa.com	
105)	World Plus	51 100 WP	02/01/12- 10/05/13	Recall affects all World Plus seats ever made. The buckle/tongue on the impact shield of affected seats may only partially engage, appearing to be fully latched when it is not. Kiddy will reimburse owners the full purchase price of the car seat. Contact mfg. (855-925-4339) for more information.
106)	Kolcraft	REFER TO OLDER MODELS LIST		
107)	Lin Lih/MCP Ent.	REFER TO OLDER MODELS LIST		

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Maxi-Cosi (Dorel)			Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com	
108)	Pria 70	CC133xxx	01/01/19 - 07/31/19	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.
109)	Pria 85 Pria 85 Max	CC121xxx, CC156xxx, CC182xxx, CC183xxx, CC191xxx, CC201xxx, CC212xxx, CC213xxx, CC217xxx, CC221xxx	01/01/19- 08/17/21	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.
110)	Mercedes-Benz USA		REFER TO OLDER MODELS LIST	
111)	Mia Moda		REFER TO OLDER MODELS LIST	
Orbit Baby			877-672-2229 / 510-793-5007 - www.orbitbaby.com	
112)	Car Seat Base G2	ORB822000	03/20/13- 07/20/13	Voluntary recall of the Orbit Baby Car Seat Base G2 with listed manufacturer dates AND with a Batch Number of A0840, A0860, or A0880. The knob on the base used to tighten the base into the vehicle may detach or spin without tightening the base. <u>The Infant Car Seat G2 is not affected by this recall and can continue to be used without the base.</u> Contact mfg. for a free repair kit.
113)	Peg Perego USA		REFER TO OLDER MODELS LIST	
114)	Playskool		REFER TO OLDER MODELS LIST	
115)	Pride Trimble/Virco		REFER TO OLDER MODELS LIST	
116)	Questor		REFER TO OLDER MODELS LIST	
Recaro			888-973-2276 / 800-873-2276 / 248-364-3818/ - www.recaropromotion.com	
117)	Performance RIDE	333.01.xxx	01/15/13 - 06/09/15	The top tether anchorage on the seat may detach from the plastic shell in a crash. Contact mfg. for repair kit.
118)	ProRIDE	332.01.xxx	04/09/10 - 06/09/15	The top tether anchorage on the seat may detach from the plastic shell in a crash. Contact mfg. for repair kit.
119)	ProSport	385.01.xxxx	06/16/10- 01/31/13	When the affected child seats are installed with the LATCH lower anchors only (without the top tether), the child's head can move too much, increasing the risk of injury in a crash. Contact mfg. for replacement labels and complete set of new instructions informing owners to discontinue use of the LATCH system when the weight of the child reaches 40 pounds.
120)	Renolux (FBS)		REFER TO OLDER MODELS LIST	
121)	Safeline Kids (See Triple Play Products also)		REFER TO OLDER MODELS LIST	

List No.	Model Name	Model No. (X = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Safety 1st (Dorel)			Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 - www.djgusa.com	
122)	OnBoard 35	IC124 FSM	05/01/11- 04/25/12	Some models were sold without a base and therefore did not provide lower LATCH attachments as required by FMVSS 213. Carriers can safely be installed without the base using the seat belt. Contact mfg. to obtain a base.
123)	Snugli			See Evenflo
124)	Strolee			REFER TO OLDER MODELS LIST
125)	Team-Text America			REFER TO OLDER MODELS LIST
126)	TriplePlay Products (See Safeline Kids also)			REFER TO OLDER MODELS LIST
127)	TRW			REFER TO OLDER MODELS LIST
WAYB			WAYB: 888-924-9292 - www.wayb.com	
128)	Pico	All models (CSTPI-##-001)	03/01/19- 05/12/19	The headrest's aluminum tubular frame can break allowing the headrest to detach. Contact mfg. for replacement headrest and instructions.
129)	XSci			REFER TO OLDER MODELS LIST

Integrated (built-into the vehicle) seats

	Manufacturer	Model Year	Customer Assistance
Chrysler			800-853-1403 / 800-992-1997
130)	Town and Country	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
131)	Town and Country	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
132)	Town and Country	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
133)	Town and Country	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.
Dodge			800-853-1403 / 800-992-1997
134)	Caravan Grand Caravan	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
135)	Caravan Grand Caravan	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
136)	Caravan Grand Caravan	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
137)	Caravan Grand Caravan	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.
Ford			800-392-3673
138)	Windstar	1998	The headrest lockout mechanism on the integrated child seats may not engage and lock the headrest in the "down" position, as intended. Replace bench seats with integrated child seats with seats built with revised headrest lockout mechanisms.
Plymouth			800-853-1403 / 800-992-1997
139)	Voyager Grand Voyager	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
140)	Voyager Grand Voyager	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
141)	Voyager Grand Voyager	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
142)	Voyager Grand Voyager	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.

Index of Recalls and Safety Notifications
For the model numbers "x" = more numbers or letters follow.

Model numbers and model names for car seats under recall are followed by their index number which corresponds to the "List No." for each listing. If the model number is not found, check the model name also. Model numbers are not available for all model names.

Notes:

- 1) Dorel Juvenile Group products are indexed under each individual product line (Alpha Elite, Alpha Sport, Beatrix Potter, Bertini, Cosco, Eddie Bauer, Maxi-Cosi, and Safety 1st) as well as under "Dorel."
- 2) Graco issued recalls in February and July 2014 on the harness buckles used on many convertible, harnessed booster, and infant seats manufactured from 2009 through January 2014. Since model #'s are not available for the model names included in this recall, Graco seats with dates from 2009 through January 2014 should be looked up by model name rather than number.

4moms		Babyhood Industries		# E9LJ93P	28
# 1032	1	ALL MODELS	15	# E9LJ93S	28
Infant Car Seat	1			# E9LK31x	32
		Basic Comfort		# E9LK32x	32
Alcot		ALL MODELS	16	# E9LK33Q	32
ALL MODELS	2			# E9LK91A	28
		Beatrix Potter (Dorel)		# E9LL11x	32
All Our Kids		ALL MODELS	17	# E9LL12x	32
ALL MODELS	3			# E9LL21A	20
		Bertini (Dorel)		# E9LL23P	20
American Motors		ALL MODELS	18	# E9LL23Y	20
ALL MODELS	6			# E9LS55T	25
		Bolform		# E9LS55U	25
Angel Guard (Merritt Manufacturing)		ALL MODELS	19	# E9LS56P	25
AngelRide Car Bed	7			# E9LS5xx	26
		Britax		# E9LS63F	22
babidéal (Dorel China America)		# E1A005R	31	# E9LS65U	25
# BC901BPXL	8	# E1A006B	31	# E9LS66C	25
Storm Booster	8	# E1A015Q	29	# E9LT34x	27
		# E1A016A	29	# E9LT35X	27
Baby Jogger		# E1A016H	29	# E9LT71Q	31
# BJ61500	10	# E1A025Q	21	# E9LT75R	31
# BJ64510	9	# E1A116L	31	# E9LT76B	31
# BJ64529	9	# E1A135Q	29	# E9LT76L	31
# BJ70411	12	# E1A183F	24	# E9LT76N	31
# BJ70424	12	# E1A185x	24	# E9LT76P	31
# BJ70431	12	# E1A186R	24	# E9LT85Q	29
# BJ72510	11	# E1A203F	24	# E9LT85S	29
# BJ80400	10	# E1A205x	24	# E9LT86A	29
City GO Car Seat	9	# E1A206x	24	# E9LT86F	29
City GO Car Seat Base	10	# E1A207E	24	# E9LT86G	29
City Mini Car Seat/Stroller	11	# E1A215x	26	# E9LT86H	29
Vue Lite Car Seat/Stroller	12	# E1A216P	26	# E9LT95N	21
		# E1A221Q	26	# E9LT95Q	21
Baby Trend		# E1A225x	26	# E9LT95Z	21
# FB48417	13	# E1A226L	26	# E9LU63F	22
# FB58181	13	# E9L14	30	# E9LU65P	22
# FB60070	14	# E9L20	30	# E9LU65V	24
# FB60408	14	# E9L80	30	# E9LU66R	22
Hybrid 3-in-1 LX	13	# E9LG81A	20	# E9LU66x	24
TrendZ Fastback	14	# E9LG83x	20	# E9LU67x	24
		# E9LJ91x	28	# EXA116L	31
		# E9LJ92E	28	# EXA185M	24

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

Britax (continued)

EXA216L 26

EXLT34A 27

EXLU65M 22

S01298600 26

S01635200 23

S02063xxx 24, 26

S02064000 26

S03803xxx 24

S04144xxx 24

S04145000 24

S04281xxx 26

S04402800 24

S04628500 26

S04884xxx 24

S04975600 24

S04978900 24

S05260200 24

S06018800 26

S06020xxx 24, 26

S06051300 26

S06147100 24

S914900 23

S915200 23

S915400 23

S921800 24

S921900 23

S923700 26

Advocate 70-G3 20

Advocate ClickTight 21

B-Agile Travel System 23

B-Safe 35 22, 24

B-Safe 35 Elite 25, 26

B-Safe 35 Elite Travel Systems 26

B-Safe 35 Elite XE 25

B-Safe 35 Travel System 23

B-Safe 35 Travel Systems 24

B-Safe 35 XE 22

B-Safe BOB 35 27

Boulevard 70-G3 28

Boulevard ClickTight 29

Companion 30

Marathon ClickTight 31

Pavilion 70-G3 32

Century

ALL MODELS 33

Childcare

ALL MODELS 2

Chrysler [Aftermarket]

ALL MODELS 35

Chrysler [Integrated]

Town and Country 130, 131, 132, 133

Clek

F012 37

F014 37

F015 37

F016 37

F017 37

F018 37

F019 37

FL15 36

FL16 36

FL17 36

FL18 36

FL19 36

LG19U1 38, 39

LGO20U1 40, 41

Fillo 36

Foonf 37

Liing 38, 39

Liingo 40, 41

Collier-Keyworth

ALL MODELS 42

Combi

378099 43

8220 44

8220x 45

8836 46

BabyRide 43

Coccoro 44, 45

Zeus 360 46

Compass Baby

ALL MODELS 47

Cosco (Dorel)

IC123 FSM 48

Comfy Carry 48

Diono

16000 52, 53, 54

16600 52

16800 53

16900 54

300000 51, 55

30100 50

30300 55

30400 51

31200-US-01 49

31201-US-01 49

31202-US-01 49

Cambria 2 49

Olympia 50

Pacifica 51

Radian R100 52

Radian R120 53

Radian RXT 54

Rainier 55

Disney (Dorel)

ALL MODELS 56

Dodge [Integrated]

Caravan 134, 135, 136, 137

Grand Caravan 134, 135, 136, 137

Dorel (Beatrix Potter)

ALL MODELS 17

Dorel (Bertini)

ALL MODELS 18

Dorel (Cosco)

IC123 FSM 48

Comfy Carry 48

Dorel (Disney)

ALL MODELS 56

Dorel (Eddie Bauer)

ALL MODELS 58

Dorel (Maxi-Cosi)

CC121xxx 109

CC133xxx 108

CC156xxx 109

CC182xxx 109

CC183xxx 109

CC191xxx 109

CC201xxx 109

CC212xxx 109

CC213xxx 109

CC217xxx 109

CC221xxx 109

Pria 70 108

Pria 85 109

Pria 85 Max 109

Dorel (Safety 1st)

IC124 FSM 122

OnBoard 35 122

Dorel China America (babidéal)

BC901BPXL 8

Storm Booster 8

Downunder

ALL MODELS 57

Eddie Bauer (Dorel)

ALL MODELS 58

Evenflo

306xxx 60

30711365 70

308xxx 67, 69

30911118AD 59

30911120D 59

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

Evenflo (continued)		Ford [Integrated]		Snug Ride Click Conct 40	101
# 30911173AD	59	Windstar	138	SnugRide Classic Connect	98
# 3091967AD	59			TurboBooster	102
# 310xxx	65	General Motors [Aftermarket]			
# 3151198	62	ALL MODELS	78	Harmony	
# 31511xxx	62			# 9999 - All Models	103
# 3151953	62	Gerry		Big Boost Deluxe	103
# 31521138	62	ALL MODELS	79		
# 329xxx	61, 64			International	
# 34411029	75	Graco		ALL MODELS	104
# 34411686	75	# 1794333	85		
# 34411695	75	# 1794334	90	Kiddy USA	
# 34411700	63	# 1812930	82	# 51 100 WP	105
# 34411741	63	# 1813015	90	World Plus	105
# 345xxx	72	# 1813040	85		
# 346xxx	68, 73	# 1813074	90	Kolcraft	
# 371xxx	71, 74	# 1853478	90	ALL MODELS	106
# 385xxx	66	# 1871689	90		
# 46811xxx	62	# 1872691	90	Lin Lih/MCP	
# 48111xxx	62	# 1877535	90	ALL MODELS	107
# 48411xxx	62	# 1908152	90		
# 52911307A	62	# 1910130	88	Maxi-Cosi (Dorel)	
# 52921040	62	# 1923980	88	# CC121xxx	109
# 55311xxx	62	# 1924519	95	# CC133xxx	108
Big Kid Booster	59	# 1924520	95	# CC156xxx	109
Chase DLX	61	# 1926538	88	# CC182xxx	109
Chase Factory Select	60	# 1926539	88	# CC183xxx	109
Chase LX	60, 61	# 1954477	86	# CC191xxx	109
Chase Select	60	# 1963973	102	# CC201xxx	109
Embrace 35	62	# 1963974	102	# CC212xxx	109
Evolve 3-in-1	63	# 1963975	102	# CC213xxx	109
Express Factory Select	64	# 1963976	102	# CC217xxx	109
Maestro	65	# 1967886	102	# CC221xxx	109
Maestro Factory Select	65	# 1975173	102	Pria 70	108
Momentum 65	66	Aprica A30	80	Pria 85	109
Momentum 65 DLX	66	Argos 70	81	Pria 85 Max	109
Secure Kid 100	67	Argos 70 Elite	81		
Secure Kid 300	67	Classic Ride	82	Mercedes-Benz USA	
Secure Kid 400	67	Classic Ride 50	83	ALL MODELS	110
Secure Kid LX	67	ComfortSport	84, 85		
Secure Kid LX Factory Sel	67	Extend2Fit	86	Merritt Manufacturing (Angel Guard)	
Snugli All-in-One	68	Head Wise 70 + SftySurnd	87	AngelRide Car Bed	7
Snugli Booster	69	Milestone	88		
Snugli Embrace 35	70	My Ride 65	89, 90	Mia Moda	
SureRide DLX	71	My Ride 65 + SftySurnd	89	ALL MODELS	111
Symphony	73	My Ride 70	91		
Symphony 65 DLX	72	My Size 70	92	Orbit Baby	
Symphony 65 E3	73	Nautilus 3-in-1	93	# ORB822000 (Base)	112
Symphony DLX	72	Nautilus Elite	93	Car Seat Base G2	112
Symphony LX	72	Nautilus Plus	93		
Titan 65	74	Ready Ride	94, 95	Playskool	
Titan 65 Factory Select	74	Size4Me70	96	ALL MODELS	114
Transitions	75	Smart Seat	97		
		Smart Seat + SftySurnd	97	Plymouth [Integrated]	
Fisher Price		Snug Ride	98	Grand Voyager	139, 140, 141, 142
ALL MODELS	76	Snug Ride 30	99	Voyager	139, 140, 141, 142
		Snug Ride 35	100		
Ford [Aftermarket]		Snug Ride Classic Conct 30	99	Pride Trimble/Virco	
ALL MODELS	77	Snug Ride Classic Conct 35	100	ALL MODELS	115

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

Questor	
ALL MODELS	116
Recaro	
# 332.01.xxx	118
# 333.01.xxx	117
# 385.01.xxx	119
Performance RIDE	117
ProRIDE	118
ProSport	119
Renolux (FBS)	
ALL MODELS	120
Safeline Kids (see Triple Play also)	
ALL MODELS	121
Safety 1st (Dorel)	
# IC124 FSM	122
OnBoard 35	122
Snugli	
See Evenflo	68, 69, 70
Strolee	
ALL MODELS	123, 124
Team-Tex	
ALL MODELS	125
TriplePlay Products	
ALL MODELS	126
TRW	
ALL MODELS	127
WAYB	
# CSTPI-##-001	128
Pico	128
XSci	
ALL MODELS	129